## **Vehicle Inspection Form**

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year 1983 Make For	d Model	1000gal. Asphalt Distributor GVW-19,700LBS.
VIN: 1 F D N F 6 0 H 4 D V A 2 2 3 2 6 Title Restriction: DY N N Odometer: 6 0 7 9 5 4 Miles DKilometers Odometer Accurate DY DN:		
Long Description:  This Vehicle:  Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only  Engine- Type:  L, V351co.in.  Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid  Engine Condition:  Runs Needs repair is in unknown condition  Repairs needed:		
This vehicle was maintained every 3000 Days Hours Miles  Date Removed From Service: 2010 Maintenance Records: Available Not Available For Inspection  Transmission: Automatic Manual 4 Speed Condition: Operable Needs repair Is Unknown Condition  Repairs Needed: 2 Speed Rear Axe/		
Drivetrain:   2 Wheel Drive □ 4 Wheel Drive Condition: Good  Exterior: Color: Yellow Windows: □ No Cracked Glass □ Cracked  Minor: ☑ Dents □ Scratches □ Dings Tire Condition: Fq'r Tread: #Flat Hubcaps #  Major Damage to: Tire Wheather Cracked		
Additional Damage: Decals Remain  Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions  Emergency equip: None Has been removed & There are holes in the exterior There are no holes  Interior: Color Brown Cloth Vinyl Leather		
Damage to Seats:		
Additional Equipment: Wisconsin Motor and Pump - Spray Barin Good Shape  Manufacturer Wisconsin Model Serial #  Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type  Location of Asset:		
For more information contact:  Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		

March 4, 2019 (Exhibit #11)