

Generic Inspection Form

Inventory ID: _____

Asset Number _____

Anticipated Sale Price: _____

Short Description: Eager Beaver Tilt-Top Trailer

Year _____

Manufacturer _____

Model _____

Please fill in or check if apply

Long Description:

This Equipment: Is Operable Is Not Operable For Parts Only Needs Repair The Condition is Unknown

Hours: _____ This equipment was maintained every _____ Hours Days

Serial # 112 TXT20XBA160006

Repairs needed: _____

Description of Use

Trailer used for hauling equipment.
Has a rebuilt good lifting cylinder. Has pindale hitch.

Color Yellow Cloth Vinyl Leather Metal Plastic Wood Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Comments:

This trailer was completely rewired and a new trailer
breakaway kit was installed with new lights.

Thornhill Trucking Co. - cost \$2096.55

Location of Asset: _____

For more information contact: _____

March 4, 2019
(Exhibit #12)