

Generic Inspection Form

Inventory ID: _____

Asset Number _____

Anticipated Sale Price: _____

Short Description: 24 Foot Backhoe Trailer

Year _____

Manufacturer Belshe

Model T-2

Please fill in or check if apply

Long Description:

This Equipment: Is Operable Is Not Operable For Parts Only Needs Repair The Condition is Unknown

Hours: _____ This equipment was maintained every _____ Hours Days

Serial # 16JFOJ628K10208106089

Repairs needed: none - Six wheel Trailer, Tires good, pindale hitch, Pearling metal floor - with wood up front, ramps good

Description of Use

Backhoe Trailer - Newer Bulldog Jack - Capacity Lift 10,000 LBS. Gross Axle wt. rating - Front 6000 - Rear 6000 LBS.

Color Yellow Cloth Vinyl Leather Metal Plastic Wood Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: 24 Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____

March 4, 2019
(Exhibit # 20)