

Generic Inspection Form

| | | |
|---|---|-------------------------------|
| Inventory ID: _____ | Asset Number _____ | Anticipated Sale Price: _____ |
| Short Description: <u>Homelite 3inch Trash Pump</u> | | Pump Model No. <u>HIP3</u> |
| Year _____ | Manufacturer <u>Homelite - Pump</u> <u>Honda Motor</u> | Model <u>Unit. No. 01602A</u> |

Please fill in or check if apply

Long Description: Homelite 3inch Trash Pump
Honda Motor

This Equipment: Is Operable Is Not Operable For Parts Only Needs Repair The Condition is Unknown

Hours: _____ This equipment was maintained every ^{before} it was Hours Days
_{used}

Serial # HR 179 004 D

Repairs needed: (motor does not run)

Description of Use

Pumping only water.

Color _____ Cloth Vinyl Leather Metal Plastic Wood Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer Honda Motor Model GX 240-242 cm³

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: Motor doesn't run.

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Comments: _____

Location of Asset: _____

For more information contact: _____

March 4, 2019
(Exhibit # 23)