

Heavy Equipment Inspection Form

Inventory ID:	Asset Number	Fair Market Value:
Short Description: <u>Vermeer Tree Chipper 1220</u>		
Year _____	Manufacturer <u>Vermeer</u>	Model <u>1220 BC</u>
Long Description: Equipment Serial # <u>4VRD15M1000188</u> [Required for all Marketing]		
Motor ID No. <u>LD33776V470960V</u>		
This Equipment: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Is Operable <input type="checkbox"/> Is not operable <input type="checkbox"/> For Parts Only		
Engine: <u>L, V 4 cyl.</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel engine Engine: <input checked="" type="checkbox"/> Hours <u>2533.9</u> <input type="checkbox"/> Miles _____		
This vehicle was maintained every <u>200</u> <input checked="" type="checkbox"/> Hours		
Engine Manufacture: <u>Perkins</u> Condition: <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Engine Repairs needed: <u>Motor is good.</u>		
Transmission: <input type="checkbox"/> Automatic <input type="checkbox"/> Manual _____ Speed Transmission: <input type="checkbox"/> Hours _____ <input type="checkbox"/> Miles _____		
Transmission Manufacture: <u>Perkins</u> Condition: <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown		
Transmission Repairs Needed: <u>none</u>		
Drivetrain: <input type="checkbox"/> 2WD <input type="checkbox"/> 4WD <input type="checkbox"/> AWD Condition: _____		
Date Removed From Service: <u>2009</u> Maintenance Records: <input checked="" type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Exterior: Color <u>Yellow</u> Windows: <input type="checkbox"/> No cracked glass <input type="checkbox"/> Cracked _____		
Minor <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat _____		
Damage to: <u>Tires good condition - 1 new one.</u>		
Additional Damage to: _____		
# Of Wheels _____ # Of Axles <u>1</u> # Of Tracks _____		
Dimensions: _____		
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions		
Interior: Color _____ <input type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather		
Damage to Seats: _____		
Damage to Dash/ Floor: _____		
Radio: Brand _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD		
<input type="checkbox"/> Cruise Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Seats <input type="checkbox"/> AC <input type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown		
Additional Equipment: Manufacturer _____ Model _____		
Serial # _____ Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Description: <u>This chipper started shredding the trees in long strips instead of chips. The cutting edge barrels are OK, it was the enclosure where the barrels are located is badly worn - too much clearance between the barrels and the housing.</u>		
Location of Asset: _____		
For more information contact: _____		

March 4, 2019
(Exhibit # 26)