

Heavy Equipment Inspection Form

Inventory ID:	Asset Number	Fair Market Value:
Short Description: <u>Etnyre Chip Spreader</u>		
Year <u>1968</u>	Manufacturer <u>Etnyre</u>	Model _____
Long Description: Equipment Serial # <u>K3393-Vin No. IA51546</u> [Required for all Marketing]		
This Equipment: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Is not operable <input type="checkbox"/> For Parts Only		
Engine: <u>L, V</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel engine Engine: <input type="checkbox"/> Hours _____ <input type="checkbox"/> Miles _____		
This vehicle was maintained every <u>before use</u> <input type="checkbox"/> Hours		
Engine Manufacture: <u>International</u> Condition: <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Engine Repairs needed: <u>Machine needs the fuel tank either cleaned out or replaced - has trash in the tank.</u>		
Transmission: <input type="checkbox"/> Automatic <input checked="" type="checkbox"/> Manual _____ Speed _____ Transmission: <input type="checkbox"/> Hours _____ <input type="checkbox"/> Miles _____		
Transmission Manufacture: <u>International</u> Condition: <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown		
Transmission Repairs Needed: <u>none</u>		
Drivetrain: <input checked="" type="checkbox"/> 2WD <input type="checkbox"/> 4WD <input type="checkbox"/> AWD Condition: <u>good</u>		
Date Removed From Service: <u>2011</u> Maintenance Records: <input checked="" type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Exterior: Color <u>Yellow</u> Windows: <input type="checkbox"/> No cracked glass <input type="checkbox"/> Cracked <u>none</u>		
Minor <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat _____		
Damage to: <u>Tires are runable and will hold air - but are weather cracked.</u>		
Additional Damage to: <u>Conveyor Belts are in good condition</u>		
# Of Wheels <u>4</u> # Of Axles <u>1 Rear Axle</u> # Of Tracks _____		
Dimensions: <u>Rock Screen - good condition</u> <u>Front walkway good. Rock levers good condition.</u>		
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions		
Interior: Color <u>Black</u> <input type="checkbox"/> Cloth <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Leather		
Damage to Seats: <u>none</u>		
Damage to Dash/ Floor: <u>none</u>		
Radio: Brand <u>none</u> <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD		
<input type="checkbox"/> Cruise Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Seats <input type="checkbox"/> AC <input checked="" type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown		
Additional Equipment: Manufacturer _____ Model _____		
Serial # _____ Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Description: <u>Motor and machine runs and operates good.</u>		
Location of Asset: _____		
For more information contact: _____		

March 4, 2019
(Exhibit # 27)