

Heavy Equipment Inspection Form

Inventory ID:	Asset Number	Fair Market Value:
Short Description: <u>Amz Pot Hole Patching Machine</u>		
Year _____	Manufacturer <u>Zimmerman Equip. Co.</u>	Model <u>AMZ MAGNUM</u>
Long Description: Equipment Serial # <u>0828AAA111BA111BC</u> [Required for all Marketing]		
This Equipment: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Is Operable <input type="checkbox"/> Is not operable <input type="checkbox"/> For Parts Only Engine: <input type="checkbox"/> L, V <input type="checkbox"/> Gas <input type="checkbox"/> Diesel engine Engine: <input checked="" type="checkbox"/> Hours <u>725.3</u> <input type="checkbox"/> Miles _____ This vehicle was maintained every _____ <input type="checkbox"/> Hours <u>Wisconsin 4 cylinder motor</u>		
Engine Manufacture: <u>Wisconsin</u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is in Unknown Condition Engine Repairs needed: _____		
Transmission: <input type="checkbox"/> Automatic <input type="checkbox"/> Manual _____ Speed Transmission: <input type="checkbox"/> Hours _____ <input type="checkbox"/> Miles _____ Transmission Manufacture: _____ Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown Transmission Repairs Needed: _____		
Drivetrain: <input type="checkbox"/> 2WD <input type="checkbox"/> 4WD <input type="checkbox"/> AWD Condition: _____ Date Removed From Service: <u>2008</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection		
Exterior: Color _____ Windows: <input type="checkbox"/> No cracked glass <input type="checkbox"/> Cracked _____ Minor <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat _____ Damage to: _____ Additional Damage to: _____ # Of Wheels <u>4</u> # Of Axles <u>2</u> # Of Tracks _____ Dimensions: _____ Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input checked="" type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions <u>Decals remain</u>		
Interior: Color _____ <input type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: _____ Damage to Dash/ Floor: _____ Radio: Brand _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD <input type="checkbox"/> Cruise Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Seats <input type="checkbox"/> AC <input type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown		
Additional Equipment: Manufacturer <u>Roots Blower</u> Model _____ Serial # _____ Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Description: <u>Machine a Roots Blower that supplies compressed air to air tank, IMS Air Compressor. Insulated Asphalt Tank with a heating system that is 110vatt system.</u>		
Location of Asset: _____ For more information contact: _____		

March 4, 2019
(Exhibit #29)